

MIWA Q68046
LAMP SOCKET AND SOCKET ASSEMBLY
Filed: January 11, 2002
Darryl Mexic 202-293-7060
1 of 6








FIG. 2






FIG.3

Q68046 MIWA LAMP SOCKET AND SOCKET ASSEMBLY

Filed: January 11, 2002
Darryl Mexic 202-293-7060
3 of 6







MIWA Q68046 LAMP SOCKET AND SOCKET ASSEMBLY Filed: January 11, 2002 Darryl Mexic 202-293-7060

4 of 6





FIG.6

|e=b iŦ

[]

--5 |sab ļ.:d MIWA Q68046 LAMP SOCKET AND SOCKET ASSEMBLY

Filed: January 11, 2002 Darryl Mexic 202-293-7060 5 of 6






FIG.8



MIWA Q68046
LAMP SOCKET AND SOCKET ASSEMBLY
Filed: January 11, 2002
Darryl Mexic 202-293-7060
6 of 6

